

INSPECTION REPORT

Inspector's Name Fought, Matthew			Inspector's Signature				Inspector's ID No. S3703	Report No. 139	Date yy mm dd 2021 12 13				
Railroad/Company Name & Address NEW HOPE VALLEY RWY/NC RR MUSEUM P.O. Box 40 New Hope Valley Railroad New Hill NC 27562					R/C R	Division SYSTEM	RR/Co. Representative (Receipt Acknowledged) Name Chris Tilly Title President Email COLTilly@aol.com Signature _____ Sent VIA email						
From: City NEW HILL		Codes 3255	Destination City & County				Codes	From Latitude					
State NC		37	City NEW HILL				3255	From Longitude					
County WAKE		C183	County WAKE				C183	To Latitude					
Mile Post: From 0010.30 To 0014.10			Inspection Point NEW HILL, NC				To Longitude						
Activity Code:	HGCS	ENSS	GXIR	ENSR									
Units:	1	4	1	1									
Sub Units:	4	5	3	1									
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1	10.30			234	0245	A1			735491H	N	N	2	HGCS
Description SIGN NOT CLEARLY VISIBLE TO HIGHWAY USER. Daisey St - Visual unaccompanied inspection only. Both "2 Tracks" signs in poor condition and not reflective.													
Seal Applied		Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				Latitude:				Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?					
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
2	10.30			234	0241	A1			735491H	N	N	1	HGCS
Description INSULATED WIRE NOT PROTECTED FROM MECHANICAL INJURY. Daisey St - Visual unaccompanied inspection only. Exposed cable/wire going into bottom of junction box on signal on the west side of the crossing.													
Seal Applied		Seal Removed			Hazard Class			UN/NA ID					
Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				Latitude:				Longitude:					
Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional				Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?					

INSPECTION REPORT

(Continuation)

Inspector's ID No. S3703	Report No. 139	Report Date 12/13/2021
-----------------------------	-------------------	---------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
3	10.30			234	0217	B2			735491H	N	N	8	HGCS

Description
 ROUNDELS OR REFLECTORS NOT MAINTAINED IN GOOD CONDITION.
 Daisy St - Visual unaccompanied inspection only. Dirty lights.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
4	10.30			234	0305	H2			735491H	N	N	2	ENSS

Description
 FAILURE TO HAVE EITHER A LIVE PERSON ANSWER CALLS DIRECTLY OR USE AN AUTOMATED ANSWERING SYSTEM FOR RECEIVING CALLS
 Daisy St - When calling emergency contact number on ENS sign, it rings and then goes to a voicemail which says its full and cannot receive anymore messages.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
5	10.30			234	0309	C111			735491H	N	N	2	ENSS

Description
 ANY ENS SIGN FAILS TO BE RETROREFLECTIVE.
 Daisy St - Both ENS signs.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

INSPECTION REPORT

(Continuation)

Inspector's ID No. S3703	Report No. 139	Report Date 12/13/2021
-----------------------------	-------------------	---------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
6	10.30			234	0403	B			735491H	N	N	1	GXIR

Description
FAILURE TO COMPLETE INVENTORY FORM (OR ELECTRONIC EQUIVALENT) IN ACCORDANCE WITH THE INVENTORY GUIDE
Daisey St - Overdue for update along with Section I. 23 & 33 incorrect.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
7	10.40			234	0311	AII			735493W	N	N	2	ENSS

Description
THE MAINTAINING RAILROAD, OR THE RAILROAD APPOINTED PURSUANT TO 234.306(B), FOR A HIGHWAY-RAIL OR PATHWAY GRADE CROSSING FAILS TO PLACE AND MAINTAIN A SIGN ON EACH APPROACH TO THE CROSSING THAT CONFORMS TO 234.309, EXCEPT AS PROVIDED IN PARAGRAPH (A)(2) OF THIS SECTION.

Bonsal Crossing Rd - No ENS signs.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
8	12.1			234	0403	B			466355P	N	N	1	GXIR

Description
FAILURE TO COMPLETE INVENTORY FORM (OR ELECTRONIC EQUIVALENT) IN ACCORDANCE WITH THE INVENTORY GUIDE
Horton Rd - Overdue for update along with Section I. 33 incorrect.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

INSPECTION REPORT

(Continuation)

Inspector's ID No. S3703	Report No. 139	Report Date 12/13/2021
-----------------------------	-------------------	---------------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
9	12.1								466355P	N	N	0	

Description - [** Comment to Railroad/Company **]
Horton Rd - Need to add yield/stop sign per MUTCD Standard Section 8B.04 (yield sign is preferred over stop sign) Also missing yellow W-10 Advance Warning sign on east side of the crossing.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
10	14.1			234	0403	B			722596J	N	N	1	GXIR

Description
FAILURE TO COMPLETE INVENTORY FORM (OR ELECTRONIC EQUIVALENT) IN ACCORDANCE WITH THE INVENTORY GUIDE
New Hill Olive Chapel Rd - Overdue and section I. 33 is blank.

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------

Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
11	14.1			234	0311	B1			722596J	N	N	1	ENSS

Description
FAILURE TO PROPERLY LOCATE AND MAINTAIN THE SIGN(S) AT CROSSING
New Hill Olive Chapel Rd - Missing ENS sign and crossbuck on north side of crossing. Also need to add yield/stop sign per MUTCD Standard Section 8B.04 (yield sign is preferred over stop sign)

Seal Applied	Seal Removed	Hazard Class	UN/NA ID
--------------	--------------	--------------	----------

Violation Recommended <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Latitude:	Longitude:
---	-----------	------------

Written Notification to FRA of Remedial Action is: <input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional	Railroad Action Code	Date(mm/dd/yyyy):	Comments on back?
---	----------------------	-------------------	-------------------